

**NABAKEM**<sup>®</sup>  
Chemicals & Aerosol



PR-50A

PAINT REMOVER PR-50A,P(Paint & Gasket Remover)

**Packaging** Aerosol 420ml/can, 20cans/Box

**Unit :**

## Features

---

- Strong permeability
- Quick exfoliation
- Dropdown not found, making surroundings clean.
- Non-corrosive to all metals

## Uses

---

- Removal of gasket and paint
- Exfoliation of enamel, lacquer, varnish etc.
- Exfoliation of epoxy resin

- Removal of adhesive marks
- Removal of carbonates of casting in injection molding
- Removal of carbon residues
- Exfoliation of enamel film of copper wire

## How to Use

---

- Spray method: Apply the product evenly to the exfoliation target.  
After a time, rub it by using scraper or brush to remove carbonate.
  - Dipping method: Long-time dipping of target object causes exfoliation due to chemical action.  
Paint film expands to become bloated.
- When exfoliation is finished, clean the target by using soft cloth or high pressure water.



사용전



사용후

## Cautions

---

- Keep it in the well-ventilated place below 40°C.
- Flush contaminated skin immediately with copious quantities of water.
- Flush contaminated eye(s) immediately with copious quantities of water.
- Medical assistance should be sought immediately.
- Flush contaminated working clothes with water.
- Open the cap slowly with care.
- Sudden cap opening can cause make can pop up when inner pressure is high.
- Wrap the cap with cloth to open it.